

Approved For Release 2008/01/17 : CIA-RDP83-00418R006000100001-2

**Page Denied**

Approved For Release 2008/01/17 : CIA-RDP83-00418R006000100001-2

PROCESSING COPY

3005784

## INFORMATION REPORT INFORMATION REPORT

## CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

S-E-C-R-E-T

COUNTRY	Poland	REPORT	
SUBJECT	1. Construction of Landing Craft at Pleniewo 2. Repair Yard at Swinoujscie	DATE DISTR.	11 September 1956
		NO. PAGES	1 25X1
		REQUIREMENT NO.	RD
DATE OF INFO.		REFERENCES	25X1
PLACE & DATE ACQ.			

SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE.

1. In July 1956 the shipyard in Pleniewo (Stocznia Wislana w Pleniewo) (Flehnendorf - Q55/Y52) was continuing to construct small landing craft of wood. The vessels can carry twenty men and their equipment. Personnel strength of the shipyard is about 100 men. 25X1
2. In April 1956 there was a small floating dock in the repair yard basin at Swinoujscie (Swinemuende). Two large MTB's were in the floating dock. On the spit of land east of the basin, 10 MTB's were drawn up on shore. At the northern part of the west wharf, seven large MTB's were moored. They had radar domes, rather high signal masts, and torpedo tubes on each side amidships. Eight MTB's were moored in pairs in the south part of the basin. The MTB's in the water were flying the Soviet naval flag.
3. The area around the repair yard is being used by the Soviet Navy.

25X1

25X1

S-E-C-R-E-T

25X1

STATE	X	ARMY	X	NAVY	X	AIR	X	FBI		AEC									
(Note: Washington distribution indicated by "X"; Field distribution by "#".)																			

INFORMATION REPORT INFORMATION REPORT

**Page Denied**